





- New notification icon for SOTA Update Pending
- With the WI-FI change below, SOTA will be available for all InControl Touch Pro Vehicles with this software

## **WI-FI**

- Systems that were previously unable to connect to Wi-Fi can now do so, this enables SOTA for these vehicles

## **ISSUES FIXED IN THIS RELEASE**

### **GENERAL/SYSTEM**

- General performance improvements
- General stability improvements
- The issue of no audio being available for a whole drive cycle seen in 19A is fixed in this update
- Side Panel theme will no longer change when the date format is changed

### **AUDIO QUALITY**

- The user should no longer hear sporadic popping sounds coming from the speakers

### **SMART PHONE PACK**

- Improved google maps navigation audio when playing media using Android Auto
- When a phone is connected by Android Auto the phone will no longer show as a Bluetooth® source as well
- Android Auto Icon will now always disappear after the phone is disconnected
- Audio replies to questions to Android Auto will no longer sometimes be truncated
- General improved stability
- The Android phone header will now always be displayed with the Android Auto icon
- Improved display of Apple CarPlay
- General improved stability
- When playing media from Apple CarPlay it will be displayed in the media view
- The issue of the receiver of an outgoing call made using apple CarPlay sometimes not being able to hear the caller has been fixed
- When system is set to French, messages will no longer be read out in English

- (SDARS only) Messages received when skipping through SDARS channels will no longer be lost
- Improved Baidu CarLife connectivity
- General improved stability

## **AMBIENT LIGHTING**

- Fixed the ambient lighting control screen sometimes not displaying correctly

## **BLUETOOTH®**

- (Chinese language only) Bluetooth® name will no longer change after switching media to RSE (RSE)
- Issue sometimes preventing Bluetooth® Audio playing for a drive cycle has been fixed

## **CD PLAYER**

- Improved user experience when switching between playing media with Apple CarPlay and CD

## **CLIMATE CONTROL**

- Temperature settings and adjustments will be available in the climate landing screen
- When the vehicle is in defrost mode the purify icon will be disabled as the function will not operate in defrost mode
- Third Row Climate Controls will only be available when the engine is running are they will not work when it is not.
- Temperature unit will no longer change from Celsius to Fahrenheit in Side Panel when system language changed to Portuguese
- Temperature control on rear screens will now work even when all zones are set to high
- (North American Vehicles only)Smart Climate incorrectly showing the front passenger seat occupancy status

## **CONNECTIVITY**

- Signal bars for vehicle connection strength will now display correctly
- When a phone is connected, Wi-Fi will now automatically enable after a power cycle
- Error message "Unable to connect (015)" has been replaced with the more appropriate 'Data limit reached. Add more mobile data to continue using (name of feature being used) and try again.'

## **RADIO**

- Improved DAB reliability
- (Head Up Display (HUD)vehicles only) Media information for DAB radio will now be displayed correctly in the HUD

- (InControl touch pro Duo only) Interactive Display Module 'A' (IDMA) will now show AM not FM when AM radio is playing
- SDARS will now always launch first time
- SDARS screen will now load correctly every time
- The correct song will now always play when selected from the satellite radio play list
- General stability improvements

## **DUAL VIEW SCREENS**

- Improved DVD play back image when a display theme is selected
- White patch in settings icon of Bluetooth® browse view settings icon in Dual view has been removed

## **ECO DATA SCREEN**

- Improved accuracy for ECO data when climate control is in ECO mode

## **FORWARD TRAFFIC DETECTION**

- Forward Traffic Detection alert will no longer stick on if the camera view is changed during an alert

## **PERSONALIZATION**

- Keys can now be switched to different existing profiles

## **LIVE**

- 'Live' will now launch from the 'Extra Feature's' screen every time
- Issue of 'Live' sometimes not launching has been fixed
- 'Live' will no longer skip to the first page when opening a second one.
- Issue of 'Live' applications sometimes only opening over part of the screen has been fixed

## **MEDIA PLAYER**

- General improved stability
- Improved handling of the track duration bar
- Tracks will no longer sometimes automatically pause 3 seconds before the end.
- Correct graphic will now be shown in the background of the IPC (IPC) media panel
- The issue stopping a podcast resuming after receiving then finishing a call has been fixed

## **NAVIGATION**

- Improved stability when resuming a route
- Improved accuracy of voice guidance

- Improved accuracy of safety cameras
- Empty pop up screens will no longer be displayed
- Improved "Send to Driver" from Rear screens experience
- Improved map display when traffic side panel displayed
- The map displayed in the IPC will now always match the map in the touchscreen
- Improved reliability of address summary screen when the city selected is not unique
- Improved route calculation
- General improved reliability
- (Japan vehicles only)Rear screens will no longer display the Navigation icon as it cannot be used
- Improved Traffic Info stability
- When the map license is extended, the status will update immediately
- Navigation will no longer reset after switching the IPC to full map view.
- Improved charge station searching

## **PARKING AID**

- Issue of missing parking aid beeps has been fixed
- When in reverse, the Parking aid 360 pop up will now work when selected

## **RSE**

- Rear screens will no longer activate when opening the front console panel
- Time displayed on the rear screen will now match the front Touchscreen
- "SIRIUS XM" button is now functional in "All Settings" in RSE
- Smother operation of climate on the rear screen when using the remote control
- (Rear Massage seat vehicles only) Massage location now called upper back and lower back on the rear screens to align with the front screen

## **SEAT CONTROLS**

- Passenger seat icon now correctly displayed after favorite seat settings are selected
- Climate buttons will no longer be lost if the seat screen is opened multiple times in the same ignition cycle
- The buttons for the seat massage for lower back and back are no longer swapped

## **SPEECH**

- Improved graphics of Speech tutorial
- Improved speech 'Call Contact' reliability

## **TELEVISION**

- Television reception will now recover automatically after leaving a low reception area
- Television will now only show 'No reception' when there is really no reception
- (Brazil Vehicles only) Touchscreen will no longer show a blank screen after Brazil Television runs for around 2 minutes 30 seconds and rear screen will no longer show "No reception" message

## **TERRAIN RESPONSE**

- This update will make sure comfort program is highlighted when selected
- This update will stop Terrain Response mode from blinking after being selected
- Terrain Response mode will be displayed in the correct language (not just English)

## **TEXT TO SPEECH**

- Text to Speech will now behave correctly if it is played, then stopped, then played again

## **TIMED CLIMATE**

- Timed climate will now use the same icon in both the menus it can be launched from

## **TRANSLATIONS**

- Improved Translations for all languages

## **VALET MODE**

- Improved phone reconnection reliability when exiting Valet Mode

## **WADE SENSING**

- Improved graphics on wade sensing screen when on a hill

## **WEB BROWSER**

- A horizontal scroll bar is now displayed when a web page has been zoomed into
- General speed and reliability improvements

### **KNOWN ISSUES IN THIS RELEASE**

**THERE ARE NO KNOWN ISSUES IN THIS SOFTWARE RELEASE.**